

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
12/6/00	12/6/00	8394	City of Fullerton	303 W. Commonwealth, Fullerton, Orange County	SSO	500	An estimated 500 gallons of sewage vented out of a cleanout due to a blockage in a 6" sewer line. The cause of the blockage in the sewer line was grease. The sewage flowed into a containment area, where about 450 gallons were contained, recovered, and returned to the operational sewer system. The blockage was cleared, and the affected area was cleaned up and disinfected by City of Fullerton staff.
12/9/00	12/9/00	8778	City of Huntington Beach	20921 Magnolia, Huntington Beach, Orange County	SSO	5,000	An estimated 5,000 gallons of sewage overflowed due to a sewer line blockage. The cause of the blockage was grease and debris. The majority of the spill was contained, recovered, and returned to the operational sewer system. 75 gallons of the spill discharged into the storm drain. The line was cleared and the area was cleaned up by City of Huntington Beach staff.
12/10/00	12/10/00	8781	City of Huntington Beach	7811 Talbert, Huntington Beach, Orange County	SSO	1,000	An estimated 1,000 gallons of sewage overflowed from a manhole due to a blockage. The cause of the blockage was grease. Approximately 50 gallons of the spill were recovered and returned to the operational sewer system while the rest of the spill was discharged into a local storm drain. The storm drain led to Central Park Lake (which is dry). Repairs were made and the area was cleaned up by City of Huntington Beach staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
12/15/00	12/15/00	8392	City of Fullerton	544 Riviera, Fullerton, Orange County	SSO	760	An estimated 760 gallons of sewage overflowed from a manhole due to a blockage. The cause of the blockage was roots. The spill flowed into a natural drainage ditch. 200 gallons of the spill were contained, recovered, and returned to the operational sewer system. The blockage was cleared, the affected area was cleaned up, and disinfected by City of Fullerton staff.
12/21/00	12/21/00	8790	City of Huntington Beach	7011 Warner Ave., Huntington Beach, Orange Orange	SSO	500	An estimated 500 gallons of sewage overflowed from a manhole due to a grease blockage. About 490 gallons of the spill were recovered and returned to the operational sewer system. The blockage was cleared and the area was disinfected and cleaned up by City of Huntington Beach staff.
12/23/200	12/23/00	8967	City of Anaheim	3150 W. Lincoln, Anaheim, Orange County	SSO	1,260	An estimated 1,260 gallons of sewage overflowed from a manhole due to an excess of grease in the sewer lines. The entire spill was recovered and returned to the operational sewer system. The blockage was cleared and the area was cleaned up and disinfected by City of Anaheim staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
12/24/00	12/23/00	8966	City of Anaheim	2173 W. Lincoln Ave., Anaheim , Orange County	SSO	1,500	An estimated 1,500 gallons of sewage overflowed from a manhole due to unspecified blockage. None of the spill was contained or recovered. All 1,500 gallons of the spill flowed to a nearby catch basin and percolated to the ground. The blockage was cleared, the affected area was rinsed with hydrant water by City of Anaheim staff.
12/29/00	12/28/00	8636	City of Newport Beach	725 Domingo Dr., Newport Beach, Orange County	SSO	600	An estimated 600 gallons of sewage overflowed from a manhole and discharged into a storm drain. The spill was caused by blockage due to roots and grease. The sewage spill ultimately flowed into Newport Bay, whereupon Northstar Beach was closed. The blockage was cleared and the area was cleaned by City of Newport Beach staff.
1/2/01	12/29/00	8862	Private Party	7819 View Rim, Anaheim, Orange County	SSO	6,000	An estimated 6,000 gallons of sewage overflowed from a private manhole due to grease blockage. About 3,750 gallons of the spill were recovered and returned to the operational sewer system. The rest of the spill was discharged into a local storm drain. The blockage was cleared, and the area was cleaned up and disinfected by City of Anaheim staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
1/2/01	1/2/01	8459	Private Party	10770 Hole Ave., Riverside, Riverside County	SSO	561	An estimated 561 gallons of sewage overflowed from a private lateral due to a blockage. The cause of the blockage was grease and debris. About 505 gallons of the spill were contained, recovered, and returned to the operational sewer system. The rest of the spill was discharged into a local storm drain. The line was cleared by a contract plumber and the overflow was abated. The affected area was cleaned up and disinfected by the City of Riverside.
1/2/01	12/31/01	8269	Landmark Complex, Private Party	Huntington Beach, Orange County	SSO	500	An estimated 500 gallons of sewage overflowed from a private manhole due to a blockage. The cause of the blockage was grease. The majority of the spill was contained, recovered, and returned to the operational sewer system. City of Huntington Beach staff cleared the blockage and cleaned up the affected area.
1/2/01	1/2/01	8383	Private Party Shoei Manufacturing Company.	Rancho Cucamonga, San Bernardino County	SSO	4,350	An estimated 4,350 gallons of sewage overflowed from a manhole due to line blockage caused by grease buildup. 4,000 gallons of the spill were contained, recovered, and returned to the operational sewer system, while the excess run-off entered the city storm drain which discharged into a San Bernardino County Flood Control Channel. The blockage was cleared, the area was cleaned up, and disinfected with lime by CCWD staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
1/5/01	12/29/01	8223	City of Anaheim	7805 View Rim Dr., Anaheim, Orange County	SSO	6,000	An estimated 6,000 gallons of sewage overflowed from a private manhole due to line blockage. Approximately 2,250 gallons of the spill were contained, recovered, and returned to the operational sewer system. The rest of the spill was not recovered and discharged into a local storm drain. City of Anaheim staff made repairs and cleaned up the affected area.
1/7/01	1/7/01	7463	Private Party	7421 Cool Water, Huntington Beach, Orange County	SSO	500	An estimated 500 gallons of sewage overflowed from a private manhole due to a sewer backup. The majority of the sewage discharged into a local storm drain. 75 gallons of the spill were recovered and returned to the operational sewer system. Repairs were made and the affected area was cleaned and disinfected by the City of Huntington Beach staff.
1/8/01	12/20/01	8209	Midway City Sanitation District	Goldenwest & Humboldt; Westminster; Orange County	SSO	1,000	Approximately 1,000 gallons of sewage overflowed from a manhole due to a break in the line caused by a drilling company. The amount recovered is unknown. Midway City Sanitary District repaired the line and cleaned the affected area.
1/8/01	12/28/01	8268	City of Santa Ana	1521 W. St. Andrews; Santa Ana; Orange County	SSO	1,050	An estimated 1,050 gallons of sewage overflowed due to a contractor who plugged a sewer main during construction. The entire spill was contained and returned to the sewer system. The affected area was cleaned and disinfected with bleach by the City of Santa Ana.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
1/10/01	1/10/01	8924	City of Chino Hills	Frost @ Green Valle, Chino Hills, San Bernardino County	SSO	2,000	An estimated 2,000 gallons of sewage overflowed from a manhole during a cleaning operation because a sewage line was not connected to the main line. None of the spill was recovered and discharged into a local storm drain. The line was reconnected to the main sewer line and the City of Chino Hills staff cleaned up and disinfected the affected area.
1/14/01	1/14/01	7443	Naval Weapons Station	Naval Housing Section, Seal Beach, Orange County	SSO	750	An estimated 750 gallons of sewage overflowed from a manhole due to a blockage. The cause of the blockage was grease in sewer main line. None of the spill was recovered and discharged into a local storm drain. Maintenance crew of the Naval Weapons Station cleared the blockage, placed chlorine granuals on the affected area, and rinsed it with an additional 12,000 gallons of water.
1/16/01	1/13/01	7429	Costa Mesa Sanitary District	2007 Debra Lane, Costa Mesa, Orange County	SSO	500	An estimated 500 gallons of sewage overflowed from a manhole due to a blockage. The cause of the blockage was roots. The entire spill was recovered and returned to the operational sewer system. Costa Mesa Sanitary District's staff cleared the blockage, and cleaned up the affected area.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
1/19/01	1/15/01	8680	Private Party	1100 E. Whittier Ave, Hemet, Riverside County	SSO	21,600	An estimated 21,600 gallons of sewage overflowed from 4" private lateral due to a blockage. The cause of the blockage was juice bottles, toilet paper, rugs, and other materials in the sewer line. 3,250 gallons of the spill were recovered and returned to the operational sewer system. The rest discharged into a local storm drain which in turn led to an open field where it percolated. The blockage was cleared, the area was cleaned up, and disinfected by City of Hemet staff.
1/20/01	12/29/00	8514	City of Newport Beach	L St. and E. Balboa, Newport Beach, Orange County	SSO	500	An estimated 500 gallons of sewage overflowed from a manhole due to line blockage of grease. The entire spill was contained, vactored and returned to the operational sewer system. The blockage was cleared and the affected area was cleaned up by City of Newport Beach staff.
1/27/01	1/27/01	8892	City of Orange	5018 Almond and Solona, Orange, Orange County	SSO	1,700	An estimated 1,700 gallons of sewage overflowed from a manhole due to a blockage. The cause of the blockage was roots and grease in an 8" line. None of the spill was recovered and all of it discharged into a local storm drain. The blockage was cleared; the affected area was cleaned up, and disinfected by OCSD's staff.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
1/28/01	1/27/01	8832	Costa Mesa Sanitary District	2101 Anniversary Lane, Newport Beach, Orange County	SSO	1,575	An estimated 1,575 gallons of sewage overflowed from a 4" PVC relief line due to a lift station failure. A failed Bubbler system caused both pumps in the wet well to fail, which in turn led to backup of the wet well, causing the sewage to overflow. About 300 gallons of the sewage was recovered while the rest of the spill was discharged into a local storm drain, which ended up in Newport Bay. The system will be checked and maintained for malfunctions by the Costa Mesa Sanitary District's staff.
2/1/01	1/30/01	8903	City of Orange	1745 E. Fairway, Orange, Orange County	SSO	1,500	Approximately 1,500 gallons of sewage overflowed from a manhole due to a blockage. The cause of the blockage was grease. 1,000 gallons of the spill were contained, recovered and returned to the operational sewer system. The rest of the spill discharged into a local storm drain. The blockage was cleared, the cleanup and disinfection were completed by OCSD's staff.
2/2/01	2/2/01	9005	City of Ontario	Guasti Rd.& Holt Ontario, San Bernardino County	SSO	1,500	An estimated 1,500 gallons of sewage overflowed from a clean out in the rear of the Marriot Hotel due to a blockage. The cause of the blockage was gease. City of Ontario staff assisted the private party in releasing the blockage and cleaning the affected area. About 150 gallons of the spill were recovered and the rest of the spill discharged into a storm drain and to the flood control channel. The channel empties into the Prado Basin.

SANTA ANA REGIONAL WATER QUALITY CONTROL BOARD

SEWAGE SPILL INCIDENTS (500 GALLONS AND ABOVE)

Reported Date	Date of Spill	Notif. No.	Responsible Party	Incident Location	Spill Type	Volume Spilled	Description of Incident
2/5/01	2/3/01	9003	City of Perris	4th Street and Wilkerson, Riverside County	SSO	5,000	An estimated 5,000 gallons of sewage overflowed from a manhole due to a blockage. The cause of the blockage was grease. All 5,000 gallons of the spill were recovered and returned to the operational sewer system. City of Perris staff cleared the blockage, cleaned, and disinfected the affected area.

Row(s) 1 - 59

